



## TECHNICAL SERVICE BULLETIN HONDA HIGH PRESSURE LINE

TECHNICAL SERVICE  
800-521-8510

PART #: 5760, 5776, 5777

DOCUMENT: 220266

APPLICATION(S): 2002 – 2003 HONDA ACCORD V6, HONDA CIVIC 2 DOOR BEFORE VIN  
1HGEM2...3L034854

PAGE: 1 of 1

REVISION: 4

These are general guidelines for most power steering applications. For specific instructions, please refer to a specific vehicle repair manual.

### **HIGH PRESSURE LINE:**

1. There has been a TSB on the power steering high pressure line that fits the vehicles listed above. A loose crimp in the power steering high-pressure line may cause the silencer inside the hose to shift and make a whine or whistle noise. If you experience this condition you must replace the high pressure hose.

**NOTE:** Your replacement unit may not come with the inlet pipe. If this is the case, please follow instructions below.

### **INLET PIPE:**

1. Transfer the reservoir inlet pipe to the replacement unit.
2. Replace the inlet pipe o-ring.

**NOTE:** The o-ring provided is manufactured in a special material to provide an improved seal. Failure to replace inlet pipe o-ring may cause unit to induce air into the system.