




**Technical Bulletin
Important – Please Read!!**

TBS0029 Revised: 7/2/2018

The Replacement starter may look different than the original... but the starter that you have purchased meets or exceeds the manufacturer's specifications for correct vehicle performance.



**Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM, S-S 6:00AM-2:30PM PST**




**Avertissement!
Advertencia!**

TBS0029 Revised: 7/2/2018

Le démarreur de remplacement peut sembler différent de l'original, mais le démarreur que vous avez acheté répond ou excède les spécifications du fabricant pour le bon fonctionnement du véhicule.

El motor de arranque de repuesto puede parecer diferente al original, pero el motor de arranque que ha comprado cumple o excede las especificaciones del fabricante para el funcionamiento correcto del vehículo.



**Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, S-S 6:00AM-2:30PM PST**