




Technical Bulletin
Important – Please Read!!


TBS0133 Revision Date: 5/31/2012

The replacement starter in the box may look different than the original... but the unit that you have purchased meets or exceeds the manufacturer's specifications for correct vehicle performance.

Version I



Version II



Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST



Avertissement!
Advertencia!

TBS0133 Revision Date: 5/31/2012


Le démarreur de rechange que vous trouverez dans la boîte peut paraître différent de l'original mais la pièce que vous avez achetée répond aux spécifications du fabricant, ou les dépasse, pour un fonctionnement correct du véhicule.

El motor de arranque en la caja puede verse diferente al original... pero la unidad que compro cumple o supera las especificaciones del fabricante para el funcionamiento correcto del vehículo.

Version I
Versión I



Version II
Versión II



Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST