



41-2957

Reach Cooling Group is issuing this bulletin as a supplemental installation note. The auxiliary oil cooler assembly mounting points are difficult to identify when replacing a unit. This bulletin address the radiator mounting points in conjunction with the ac condenser mounting points, both of which are required for the auxiliary cooler to mount properly.



The pictures display the radiator with numbered mounting points the correspond to the condenser. As well as lettered points corresponding to auxiliary oil cooler mounting on both the condenser and radiator. The radiator/condenser pairing is what makes up the auxiliary oil cooler mounting

