

TENSIONER CAUTION

To reduce the likelihood of tensioner sticking,
DO NOT over torque the tensioner bolts.

This can distort the plunger.

Refer to manufacturer specifications for
maximum torque value.

SA - Tensioner