

Part # C819VC

Primary 1.0 - 1.7

Secondary 7.5k - 14.5k

Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking
3. Check for oil leakage

