

# Part # C887

**Primary 1.4 - 2.2**

**Secondary 9.5k - 15.5k**

## Physical Inspection

1. Check for corrosion on terminals
2. Check for cracks or carbon tracking
3. Check for oil leakage

